# Department of Historic Resources
# Reconnaissance Level Survey

**Isle Of Wight** *DHR Id#:* **046-5071**

## *Resource Identification*

*Property Name(s):* ..... House 22224 U.S. 258 Court House Hwy. {Current}
*Property Date:* ..... ca 1920
*Address(s):* ..... 22224 U.S. 258 Court House Hwy. {Current}
*County/Independent City:* Isle Of Wight
City: .....
*State, Zip:* .....Virginia
*USGS Quad Name:* ..... WINDSOR
*Surrounding area:* ..... Rural

***National Register Eligibility Status***
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

## *Resource Description*

*Ownership Status:* ..... Private

*Primary Resource Exterior Componant Description:*

| Component | Comp Type/Form | Material | Material Treatment |
|---|---|---|---|
| Porch | Porch - 1-story, 3-bay | Wood | Porch - Post, Square |
| Roof | Roof - Gable, Side | Metal | Roof - Shingle |
| Structural System | Structural System - Frame | Wood | Structural System - Aluminum Sidin |
| Windows | Windows - Sash, double-hung | Wood | Windows - 6/6 |
| Chimneys | Chimneys - Exterior side | Brick | Chimneys - Common Bond |
| Foundation | Foundation - Solid | Brick | Foundation - Common Bond |
| Chimneys | Chimneys - Exterior end | Brick | Chimneys - Common Bond |

*Site Description:* ..... This house is located in a rural area.

*Secondary Resource Desc:* There are six outbuildings associated with this house.

*WUZIT Count:*

| No. | Wuzit Types | Historic? |
|---|---|---|
| 2 | Barn | Historic |
| 1 | Shed | Historic |
| 1 | Equipment Shed | Historic |
| 1 | Pump House | Historic |
| 1 | Summer Kitchen | Historic |
| 1 | House | Historic |

*NR Resource Count:*

# Department of Historic Resources
# Reconnaissance Level Survey

**Isle Of Wight** **DHR Id#: 046-5071**

***Individual Resource Information***

*WUZIT:* ..... Pump House

| | | | |
|---|---|---|---|
| *Est. Date of Construction:* .... | 1950 ca {Site Visit} | *Accessed?* ..... | No |
| *Primary Resource?* ..... | No | *Number of Stories:* ..... | 1.0 |
| *Architectural Style:* ..... | Other | *Condition:* ..... | Good |
| *Interior Plan Type:* ..... | | *Threats to Resource:* ..... | Transportation Expansion |

*Description:* There are six outbuildings associated with this house. To the west is a pump house. The pump house is constructed on concrete block with a gabled roof clad in standing-seam metal.

*WUZIT:* ..... Barn

| | | | |
|---|---|---|---|
| *Est. Date of Construction:* .... | 1920 ca {Site Visit} | *Accessed?* ..... | No |
| *Primary Resource?* ..... | No | *Number of Stories:* ..... | 1.0 |
| *Architectural Style:* ..... | Other | *Condition:* ..... | Good |
| *Interior Plan Type:* ..... | | *Threats to Resource:* ..... | Transportation Expansion |

*Description:* There are six outbuildings associated with this house. Southwest of the house is a barn (B) and a summer kitchen. The barn (B) is covered in weatherboard with a gambrel roof clad in standing-seam metal.

*WUZIT:* ..... Summer Kitchen

| | | | |
|---|---|---|---|
| *Est. Date of Construction:* .... | 1920 ca {Site Visit} | *Accessed?* ..... | No |
| *Primary Resource?* ..... | No | *Number of Stories:* ..... | 1.0 |
| *Architectural Style:* ..... | Other | *Condition:* ..... | Good |
| *Interior Plan Type:* ..... | | *Threats to Resource:* ..... | Transportation Expansion |

*Description:* There are six outbuildings associated with this house. Southwest of the house is a barn (B) and a summer kitchen. The summer kitchen is covered in weatherboard with a gabled roof clad in standing-seam metal. The summer kitchen also displays six-over-six wooden double-hung sash windows, a brick chimney, and brick piers for the foundation.

*WUZIT:* ..... Equipment Shed

| | | | |
|---|---|---|---|
| *Est. Date of Construction:* .... | 1950 ca {Site Visit} | *Accessed?* ..... | No |
| *Primary Resource?* ..... | No | *Number of Stories:* ..... | 0.0 |
| *Architectural Style:* ..... | Other | *Condition:* ..... | Good |
| *Interior Plan Type:* ..... | | *Threats to Resource:* ..... | Transportation Expansion |

*Description:* There are six outbuildings associated with this house. West of the house is a large equipment shed constructed of corrugated metal and concrete block with a gabled roof covered in standing-seam metal.

*WUZIT:* ..... Shed

| | | | |
|---|---|---|---|
| *Est. Date of Construction:* .... | 1930 ca {Site Visit} | *Accessed?* ..... | No |
| *Primary Resource?* ..... | No | *Number of Stories:* ..... | 0.0 |
| *Architectural Style:* ..... | Other | *Condition:* ..... | Good |
| *Interior Plan Type:* ..... | | *Threats to Resource:* ..... | Transportation Expansion |

*Description:* There are six outbuildings associated with this house. Northwest of the house is a shed with an exterior covered in corrugated metal and a gabled roof clad in standing-seam metal.

*WUZIT:* ..... Barn

| | | | |
|---|---|---|---|
| *Est. Date of Construction:* .... | 1930 ca {Site Visit} | *Accessed?* ..... | No |
| *Primary Resource?* ..... | No | *Number of Stories:* ..... | 1.0 |
| *Architectural Style:* ..... | Other | *Condition:* ..... | Good |
| *Interior Plan Type:* ..... | | *Threats to Resource:* ..... | Transportation Expansion |

*Description:* There are six outbuildings associated with this house. To the west is a barn (A). The barn (A) features a corrugated metal exterior with a gabled roof covered in standing-seam metal.

# Department of Historic Resources
# Reconnaissance Level Survey

**Isle Of Wight** **DHR Id#: 046-5071**

| | | | |
|---|---|---|---|
| *WUZIT:* ..... | House | | |
| *Est. Date of Construction:* .... | 1920 ca {Site Visit} | *Accessed?* ..... | No |
| *Primary Resource?* ..... | No | *Number of Stories:* ..... | 2.0 |
| *Architectural Style:* ..... | Other | *Condition:* ..... | Good |
| *Interior Plan Type:* ..... | | *Threats to Resource:* ..... | Transportation Expansion |

*Description:* Built c. 1920, this two-story Frame Vernacular style house features a wooden frame structural system that rests on a solid brick foundation. The exterior is covered in aluminum siding and the side-gabled roof is clad in pressed tin shingles. This house features a brick chimney at each exterior end of the main roof and a second chimney on the exterior side of the gabled addition on the west elevation. Fenestration consists of six-over-six wooden double-hung sash windows with metal awnings. The east façade features a hipped porch with square wooden supports.

### *Cemetery Information*

### *Bridge Information*

### *National Register Eligibility Information (Intensive Level Survey)*

*Historic Context(s):* ..... Domestic
Subsistence/Agriculture

*Historic Time Period(s):* ..... R- World War I to Present (1914 - Present)

*Significance Statement:* Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

### *Bibliographic Documentation*

*Reference #:* 1

*Bibliographic RecordType:* ..... Survey

*Author:* ..... CCR, Inc.

*Citation Abbreviation:* .....

*Notes:* ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

### *Ownership Information*

### *Graphic Media Documentation*

| *Medium* | *Depository ID #* | *Photo Depository* | *Date* | *File Name* |
|---|---|---|---|---|
| 35mm B & W | 8 | VDHR | 2004/07/01 | Farm Complex |

### *Cultural Resource Management (CRM) Events*

# Department of Historic Resources
# Reconnaissance Level Survey

**Isle Of Wight** ***DHR Id#:*** **046-5071**

*CRM Event* # 1,

| | |
|---|---|
| *Cultural Resource Management Event:* ..... | Phase I Survey |
| *Date:* ..... | 2004/08/31 |
| *Organization or Person:* ..... | CCR, Inc. |
| *VDHR Project ID # Associated with Event:* .. | 2002-1760 |
| *CRM Event Notes or Comments:* ..... | VDHR # 2002-1760<br>VDOT # 0460-969-101, PE-101<br>Architectural Survey, Route 460<br>Corridor Study |

*CRM Event* # 2,

| | |
|---|---|
| *Cultural Resource Management Event:* ..... | DHR Staff: Not Eligible |
| *Date:* ..... | 2004/11/18 |
| *Organization or Person:* ..... | |
| *VDHR Project ID # Associated with Event:* .. | 2002-1760 |
| *CRM Event Notes or Comments:* ..... | |